

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2SC831 (Cont'd) D4C1 3 GESY ST45C2 3 STI	2SC891 (Cont'd) DE363 3 DGE MDS26 3 MOTA	2SC936 (Cont'd) TIP550 3 TII TIP553 3 TII	2SC1009F4 MMBC1009F4 1 MOTA TMPT1009F4 3	2SC1089 MJE3439 1 MOTA 3 SGSI D44T3 3 GESY	2SC1114 (Cont'd) D64VE3 3 GESY DE293 3 DGE PTC402 3 PTC
2SC833 2N6235 1 MOTA 2N3585 3 RCA 2N6079 3 RCA D44TE4 3 GESY	2SC892 2N5946 1 MOTA D44C1 1 SGSI MRF653 1 MOTA 2N6288 3 RCA BD239 3 RCA BU407 3 APX ST44C1 3 STI	2SC937 BU204 1 MOTA BU208 1 SGSI 2SC1875 3 NECE SU160 3 MIKG TIP550 3 TII TIP553 3 TII	2SC1009F5 MMBC1009F5 1 MOTA TMPT1009F5 3	2SC1090-1 2N6603 1 MOTA 2N6604 1 MOTA NE32702 1 NECE BFR49 3 APX	2SC1115 2N5634 1 MOTA DE385 3 DGE
2SC840 2N5050 1 MOTA D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX D44T1 3 GESY DE384 3 DGE ST44C8 3 STI	2SC893 2N5946 1 MOTA D44C1 1 SGSI MRF653 1 MOTA 2N6288 3 RCA BD239 3 RCA BU407 3 APX ST44C1 3 STI	2SC939 BU326 1 SGSI MU15001 1 MOTA BU526 3 ALGG	2SC1012A D40V1 1 GESY	2SC1096 MDS26 1 MOTA	2SC1116 MJ15011 1 MOTA ST15011 3 STI SVT6250 3 TRWS
2SC840A 2N5051 1 MOTA D44T1 3 GESY DE384 3 DGE	2SC894 2N5946 1 MOTA D44C1 1 SGSI MRF653 1 MOTA 2N6288 3 RCA BD239 3 RCA BU407 3 APX D44T1 3 GESY DE384 3 DGE ST44C8 3 STI	2SC940 2N6249 1 MOTA BU326 1 SGSI 2N6674 3 PTC BU526 3 ALGG BUX41 3 SGSI D64V33 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS	2SC1013 MDS26 1 MOTA	2SC1098 MDS26 1 MOTA	2SC1117 2N6603 1 MOTA MRF901 1 MOTA BFG90A 3 APX BFQ29P 3 SIEG BFR49 3 APX
2SC852 2N5943 1 MOTA BRF95 3 APX	2SC895 2N3441 1 MOTA DE384 3 DGE	2SC941 2N6249 1 MOTA BU326 1 SGSI 2N6674 3 PTC BU526 3 ALGG BUX41 3 SGSI D64V33 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS	2SC1014 MDS27 1 MOTA	2SC1099 2N6552 1 MOTA DE49 3 DGE	2SC1118 2N6603 1 MOTA MRF901 1 MOTA BFG90A 3 APX BFQ29P 3 SIEG BFR49 3 APX
2SC861 BUS21 1 APX BUW25 1 SGSI MJ3029 1 MOTA BUW24 3 SGSI BUX16A 3 RCA BUX80 3 PHIN D44TE3 3 GESY	2SC896 2N3442 3 RCA 2N6262 3 RCA DE385 3 DGE	2SC942 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1015 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1100 BU207 1 MOTA BU208 1 SGSI 2SC1875 3 NECE SU160 3 MIKG TIP550 3 TII TIP553 3 TII	2SC1119 2N6603 1 MOTA MRF901 1 MOTA BFG90A 3 APX BFQ29P 3 SIEG BFR49 3 APX
2SC862 BUS21B 1 APX MJ3030 1 MOTA BU133 3 PHIN BUW25 3 SGSI BUX16C 3 RCA D44TE4 3 GESY	2SC897 2N3441 1 MOTA DE384 3 DGE	2SC943 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE PTC515 3 PTC SVT7534 3 TRWS TIP554 3 TII	2SC1016 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1101 BU207 1 MOTA BU208 1 SGSI 2SC1875 3 NECE SU160 3 MIKG TIP550 3 TII TIP553 3 TII	2SC1120 MP5U04 1 MOTA GESU04 3 GESY
2SC867 2N3739 1 MOTA D44T2 1 GESY 2N3585 3 RCA D42T2 3 GESY DE124 3 DGE	2SC898 2N5946 1 MOTA D44C1 1 SGSI MRF653 1 MOTA 2N6288 3 RCA BD239 3 RCA BU407 3 APX ST44C1 3 STI	2SC944 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1017 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1102 2N3739 1 MOTA 2N3585 3 RCA D42T2 3 GESY DE124 3 DGE	2SC1121 MP5U04 1 MOTA GESU04 3 GESY
2SC884 2N5050 1 MOTA D44T1 3 GESY DE384 3 DGE	2SC899 2N3442 3 RCA 2N6262 3 RCA DE385 3 DGE	2SC945 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1018 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1103 BU204 1 MOTA BU208 1 SGSI 2SC1875 3 NECE SU160 3 MIKG TIP550 3 TII TIP553 3 TII	2SC1122 MP5U04 1 MOTA GESU04 3 GESY
2SC885 2N6307 1 MOTA BU326 1 SGSI BUS22 1 APX BU526 3 ALGG BUW35 3 SGSI BUX22 3 APX BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE SVT7530 3 TRWS TIP555 3 TII	2SC900 2N5946 1 MOTA D44C1 1 SGSI MRF653 1 MOTA 2N6288 3 RCA BD239 3 RCA BU407 3 APX ST44C1 3 STI	2SC946 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1019 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1104 2N3739 1 MOTA 2N3585 3 RCA D42T2 3 GESY DE124 3 DGE	2SC1123 MP5U04 1 MOTA GESU04 3 GESY
2SC886 2N6306 1 MOTA BU326 1 SGSI BUS22 1 APX BU526 3 ALGG BUW34 3 SGSI BUX22 3 APX BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE SVT7530 3 TRWS TIP555 3 TII	2SC901 2N6306 1 MOTA BU326 1 SGSI BUS22 1 APX BU526 3 ALGG BUW34 3 SGSI BUX22 3 APX BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE PTC515 3 PTC SVT7534 3 TRWS TIP554 3 TII	2SC947 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1020 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1105 2N3739 1 MOTA 2N3585 3 RCA D42T2 3 GESY DE124 3 DGE	2SC1124 MP5U04 1 MOTA GESU04 3 GESY
2SC887 BU326 1 SGSI BUS21 1 APX MJ410 1 MOTA BU526 3 ALGG D44TE3 3 GESY IR410 3 INR RCA410 3 RCA	2SC902 2N5634 1 MOTA BU326 1 SGSI BUS22 3 ALGG DE385 3 DGE	2SC948 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1021 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1106 2N3739 1 MOTA 2N3585 3 RCA D42T2 3 GESY DE124 3 DGE	2SC1125 MP5U04 1 MOTA GESU04 3 GESY
2SC888 BUS21 1 APX MJ410 1 MOTA D44TE3 3 GESY IR410 3 INR RCA410 3 RCA	2SC903 2N5977 1 MOTA BD241 1 SGSI D42C3 1 GESY 2N6288 3 RCA 2N6486 3 RCA BD947 3 PHIN D44C6 3 GESY D44VH4 3 GESY DE182 3 DGE MDS26 3 MOTA	2SC949 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1022 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1107 2N6123 1 MOTA BD243B 1 SGSI BDT31B 1 APX BD951 3 PHIN BDX77 3 PHIN D44VM10 3 GESY DE196 3 DGE	2SC1126 MP5U04 1 MOTA GESU04 3 GESY
2SC889 BUS21 1 APX MJ410 1 MOTA D44TE3 3 GESY IR410 3 INR RCA410 3 RCA	2SC904 2N5977 1 MOTA BD241 1 SGSI D42C3 1 GESY 2N6288 3 RCA 2N6486 3 RCA BD947 3 PHIN D44C6 3 GESY D44VH4 3 GESY DE182 3 DGE MDS26 3 MOTA	2SC950 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1023 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1108 2N6123 1 MOTA BD243C 1 MOTA BDT31B 1 APX BD951 3 PHIN D44VM10 3 GESY DE196 3 DGE	2SC1127 MP5U04 1 MOTA GESU04 3 GESY
2SC890 D40D1 1 GESY MRF515 1 MOTA SD1144-1 3 THCS	2SC905 2N5840 1 MOTA BUW34 1 SGSI BUX21A 3 APX BUX32 3 RCA BUX82 3 PHIN DE163A 3 DGE SVT7523 3 TRWS	2SC951 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1024 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1109 2N6123 1 MOTA BD243B 1 SGSI BDT31B 1 APX BD951 3 PHIN D44VM10 3 GESY DE196 3 DGE	2SC1128 MP5U04 1 MOTA GESU04 3 GESY
2SC891 2N5645 1 MOTA 2N5945 1 MOTA D42C1 1 GESY 2N5945 3 THCS 2N6288 3 RCA	2SC906 2N5977 1 MOTA BD241 1 SGSI D42C3 1 GESY 2N6288 3 RCA 2N6486 3 RCA BD947 3 PHIN D44C6 3 GESY D44VH4 3 GESY DE182 3 DGE MDS26 3 MOTA	2SC952 2N5758 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA DE283 3 DGE DE385 3 DGE	2SC1025 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2SC1110 2N6123 1 MOTA BD243C 1 MOTA BDT31B 1 APX BD951 3 PHIN D44VM10 3 GESY DE196 3 DGE	2SC1129 MP5U04 1 MOTA GESU04 3 GESY